

PATHFINDER PROJECT

Description	Date	Comments	Next Steps	Owner
Underside of bridge by the SSE sub-station (R21):	Jan-18	All silt and rubble now removed.	Monitor for obstacles	HCC/FEG
Green Lane Bridge (R27): Fence across river - south of bridge.	Jan-18	Following re-grading works, the fence possibly remains as a physical obstruction to the river.	River is flowing well there currently - no further action required. Keep monitoring.	FEG
Culvert by Jones Farm (R31): Replace existing culvert with twin pipes.	Apr-19	New culvert pipes in place.	Monitor for obstacles	HCC/FEG
Underside of Stoke Bridge (R35): Remove silt deposits through the tunnel.	Jan-18	All silt and rubble now removed.	Monitor for obstacles	HCC/FEG
Underside of Bridge at Swampton (R39): Remove silt deposits through the tunnel.	Jan-18	All silt and rubble now removed.	Monitor for obstacles	HCC/FEG
Ongoing maintenance of new culvert (R31) and under road bridges (R21,R35 and R39)	Mar 20	Gary Edwards requested a follow-up meeting in Winchester. Establish what monitoring will be done, and process to remove obstructions in the future.	Monitor for obstacles	HCC/FEG
Proposed bunds	Jan-18	Colin Ponting & Yorke-Longs reluctant to install bunds in their fields. Colin is concerned about pernicious weeds taking over. Yorke-Longs are concerned with the hydrology aspects of a weight of water sitting so close to a settlement & whether groundwater might be forced upwards on the south side of a bund.	Proposal rejected.	HCC

	Not started
	In progress
	Complete/ongoing